

Sub- Place of inspection

Dt 08.02.2017

UTES have faced some problems in reconciliation of Supplier's Address for Place of inspection provided during Call registration as same is different from the address mentioned in the Purchase Order . This has led to objections from various quarters.

2. In order to rationalise and streamline the process , it has been decided that inspection shall be carried out by UTES for Railway calls at the address that has been indicated by the Purchaser in the Purchaser Order or any subsequent amendment/ letter to that effect in writing . In the absence of any specific entry in the Purchase order regarding place of inspection , inspection call will be accepted at the address mentioned in the Purchase order except for RDSO / Production unit/ Railway approved sources where factory address and office address have been specifically approved in the vendor directory .

3. Changes have been made in UTES IBS Portal for PO registration format to indicate place of inspection at the time of PO registration . All suppliers are requested to kindly note the above provisions which shall apply to all Railway Stores purchase orders . All Suppliers / vendors are therefore requested to get the Purchase order issued in accordance with above provisions or get the amendment letter issued from Purchaser so as not to face any difficulty during call registration / inspection